REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 12/12/2017 Time: 8:44 AM

Name of School Corporation: SCHOOL CITY OF HOBART SERVICE CTR Corp ID: 454730

Address of School Corporation: 200 S Hobart Rd

City:HobartZip:46342County Number:45VIN:4DRBUAAN27B380448License Number:30051Bus Number:5Make of Body:IC Corporation Year:2007

Bus Type: C Mileage: 113397

Inspection Status: O Inspected By: Tim Grayson PE: 7558

Violations - Rejected

Inspection Code Description

16-1-1 There are any leaks from the differential, pinion seal, or either rear wheel seal

Violations - Out of Service

Inspection Code	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half ($\frac{1}{2}$) inch in diameter.
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.