

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 12/12/2017 **Time:** 10:18 AM
Name of School Corporation: SCHOOL CITY OF HOBART SERVICE CTR **Corp ID:** 454730
Address of School Corporation: 200 S Hobart Rd
City: Hobart **Zip:** 46342 **County Number:** 45
VIN: 4DRBUAAN27B380448 **License Number:** 30051 **Bus Number:** 5
Make of Body: IC Corporation **Year:** 2006 **Make of Chassis:** IC Corporation **Year:** 2007
Bus Type: C **Mileage:** 113397
Inspection Status: O **Inspected By:** Tim Grayson **PE:** 7558

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.