REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	1/9/2018	Time:	10:31 AM
Name of School Co	orporation: BAU	GO COMMUNIT	Y SCHOOLS		Corp ID:	202260
Address of School	Corporation:	29125 CR 22 V	V			
City:	Elkhart	Zip:	46517		County Number:	20
VIN:	4UZAAXCT44CL	83649	License Number:	10295	Bus Number:	6
Make of Body:	Freightliner Year:	2002	Make of Chassis:	Freightliner	Year:	2002
Bus Type:	С		Mileage:	135411		
Inspection Status:	0	Inspected By:	Wes Rowlader		PE:	7427

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.