

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/11/2018	<b>Time:</b>	11:06 AM
<b>Name of School Corporation:</b>	SOUTH BEND COMM. SCHOOL CORP.	<b>Corp ID:</b>	717205		
<b>Address of School Corporation:</b>	3003 N Bendix Dr				
<b>City:</b>	South Bend	<b>Zip:</b>	46601	<b>County Number:</b>	71
<b>VIN:</b>	4DRBUAAN5CB622160	<b>License Number:</b>	2337	<b>Bus Number:</b>	116
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2011	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2012	<b>Year:</b>	2012	<b>Year:</b>	2012
<b>Bus Type:</b>	C	<b>Mileage:</b>	78646	<b>PE:</b>	8022
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Travis Harrold	<b>PE:</b>	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
90-1-5	See Notes: Any defect inspector deems a violation not listed
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
90-1-2	The trash container is greater than a fourteen (14) quart capacity
64-1-2	A lens is cracked, missing or wrong color

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**