

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/11/2018	Time:	11:06 AM		
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.			Corp ID:	717205		
Address of School Corporation:	3003 N Bendix Dr						
City:	South Bend	Zip:	46601	County Number:	71		
VIN:	4DRBUAAN5CB622160		License Number:	2337	Bus Number:	116	
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	C			Mileage:	78646		
Inspection Status:	R	Inspected By:	Travis Harrold	PE:	8022		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
90-1-5	See Notes: Any defect inspector deems a violation not listed
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
90-1-2	The trash container is greater than a fourteen (14) quart capacity
64-1-2	A lens is cracked, missing or wrong color

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.