

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 1/17/2018	<b>Time:</b> 10:41 AM	
<b>Name of School Corporation:</b> DECATUR COUNTY COMM. SCHOOL	<b>Corp ID:</b> 161655		
<b>Address of School Corporation:</b> 1645 W SR 46			
<b>City:</b> Greensburg	<b>Zip:</b> 47240	<b>County Number:</b> 16	
<b>VIN:</b> 4UZABRDD48CZ10899	<b>License Number:</b> 31564	<b>Bus Number:</b> 5	
<b>Make of Body:</b> Freightliner	<b>Year:</b> 2007	<b>Make of Chassis:</b> Freightliner	<b>Year:</b> 2008
<b>Bus Type:</b> C	<b>Mileage:</b> 100710		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-4	See Notes: Any defect inspector deems a violation not listed
46-1-2	Any seat back or bottom is loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.