REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	1/18/2018	Time:	11:01 AM
Name of School Co	orporation: SOU	TH VERMILLIO	N COMM SCH COF	RP.	Corp ID:	838020
Address of School	Corporation:	PO Box 387				
City:	Clinton	Zip:	47842		County Number:	83
VIN:	4DRBUAAP89B681	732	License Number:	32902	Bus Number:	18
Make of Body:	IC Corporation Year	: 2007	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	С		Mileage:	68953		
Inspection Status:	0	Inspected By:	Tyler VanNess		PE:	7583

Violations - Rejected

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.