REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	1/22/2018	Time:	12:16 PM
Name of School	•	FRANKFORT CO		OOLS	Corp ID:	121170
Address of School Corporation:		50 S Maish Rd				
City:	Frankfort	Zip:	46041		County Number:	12
VIN:	1BABHCPH41F09	9347	License Number:	17739	Bus Number:	18
Make of Body:	Blue Bird Corporation	Year: 2001	Make of Chassis:	Blue Bird Corporation	Year:	2001
Bus Type:	D		Mileage:	115491		
Inspection Status:	R	Inspected By:	Nate King		PE:	7421

Violations - Rejected

Inspection Code	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal
62-1-2	One (1) taillight or one (1) brake light does not function
52-1-4	Any shock absorber is broken or missing
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.