REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 1/30/2018 | Time: | 9:05 AM |
|----------------------------------|-------------------------------------|----------------------------|----------------------|--------------------------|-------------------|------------|
| Name of School Address of School | Corporation: SHO | OALS COMM. 11741 Ironto | SCHOOL CORP on Rd | | Corp ID: | 515520 |
| City: | Shoals | Zip: | 47581 | | County Number: | 51 |
| VIN: | 4UZABRDC48CZ10604 | | License Number: | B952D | Bus Number: | 11 |
| Make of Body: | Thomas Built Buses, Yea Inc. | r: 2007 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2008 |
| Bus Type: | С | | Mileage: | 74933 | | |
| Inspection Status: | R | Inspected By: | Kelly Hammond | d | PE: | 6682 |

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.