

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/25/2018	Time:	9:17 AM		
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.			Corp ID:	454615		
Address of School Corporation:	8855 Wicker Ave						
City:	St John	Zip:	46373	County Number:	45		
VIN:	4DRBUAAN1GB732080		License Number:	9403	Bus Number:	56	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	C			Mileage:	51673		
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.