

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/31/2018	Time:	10:29 AM
Name of School Corporation:	M.S.D. WAYNE TOWNSHIP	Corp ID:	495375		
Address of School Corporation:	4205 W Morris St				
City:	Indianapolis	Zip:	46241	County Number:	49
VIN:	4drbuaan3db198446	License Number:	3946	Bus Number:	103
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
		Year:	2013		
Bus Type:	C	Mileage:	64560		
Inspection Status:	O	Inspected By:	John Pang	PE:	6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
34-1-5	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
64-1-2	A lens is cracked, missing or wrong color
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.