REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	1/29/2018	**Time:**	8:13 AM
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			**Corp ID:**	485245
Address of School Corporation:	7916 W 300 N				
City:	Anderson	**Zip:**	46011	**County Number:**	48
VIN:	1GB3G3BG5B1153334	**License Number:**	5555	**Bus Number:**	A6
Make of Body:	Girardin Minibus, Inc. **Year:** 2011	**Make of Chassis:**	Chevrolet	**Year:**	2011
Bus Type:		**Mileage:**	34655		
Inspection Status:	R	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4” min), 2 40”x40”x56” triangular bandages, 6 3”x3” gauze pads, 4 2”x4.1 yard rolls of gauze, 3 oval eye pads, 1 1”x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description