

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	1/29/2018	<b>Time:</b>	8:13 AM
<b>Name of School Corporation:</b>	FRANKTON-LAPEL COMM. SCHLS.	<b>Corp ID:</b>	485245		
<b>Address of School Corporation:</b>	7916 W 300 N				
<b>City:</b>	Anderson	<b>Zip:</b>	46011	<b>County Number:</b>	48
<b>VIN:</b>	1GB3G3BG5B1153334	<b>License Number:</b>	5555	<b>Bus Number:</b>	A6
<b>Make of Body:</b>	Girardin Minibus, Inc.	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2011
<b>Bus Type:</b>		<b>Mileage:</b>	34655		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

### Violations - Out of Service

Inspection Code Description

Bus Type Description