

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/1/2018	Time:	2:57 PM
Name of School Corporation:	SOUTH RIPLEY COMM. SCHOOL CORP	Corp ID:	696865		
Address of School Corporation:	PO Box 690				
City:	Versailles	Zip:	47042	County Number:	69
VIN:	4UZAAXCT84CL82925	License Number:	19558	Bus Number:	114
Make of Body:	Thomas Built Buses, Inc.	Year:	2002	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	137185		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-4	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-1	Any headlight is inoperative
58-1-1	Any stirrup step or handle is broken, loose or missing
58-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.