

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 2/9/2018 **Time:** 10:32 AM
Name of School Corporation: BETHESDA BAPTIST CHURCH & SCHOOL **Corp ID:** 323318
Address of School Corporation: 7950 N CR 650 E
City: BROWNSBURG **Zip:** 46112 **County Number:** 32
VIN: 1GDL7T1E82J509458 **License Number:** B891A **Bus Number:** 1
Make of Body: GMC **Year:** 2002 **Make of Chassis:** GMC **Year:** 2002
Bus Type: C **Mileage:** 108818
Inspection Status: O **Inspected By:** Jeff Kastenschmidt **PE:** 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-2	There are intersecting cracks in the windshield area covered by the wipers

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.