# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 2/14/2018 | **Time:** | 9:59 AM |
| **Name of School Corporation:** | SOUTHWESTERN JEFFERSON CO SCH CORP | | | | **Corp ID:** | 394000 |
| **Address of School Corporation:** | 239 Main St | | | | | |
| **City:** | Hanover | **Zip:** | 47243 | | **County Number:** | 39 |
| **VIN:** | 1GBJG316681210844 | | **License Number:** | 77528 | **Bus Number:** | R3 |
| **Make of Body:** | Chevrolet **Year:** | 2008 | **Make of Chassis:** | Chevrolet | **Year:** | 2008 |
| **Bus Type:** | B | | **Mileage:** | 68707 | | |
| **Inspection Status:** | A | **Inspected By:** | Troy Boyd | | **PE:** | 5171 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**