

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/19/2018 **Time:** 2:58 PM
Name of School Corporation: KOKOMO SCHOOL CORPORATION **Corp ID:** 343500
Address of School Corporation: 620 W Deffenbaugh
City: Kokomo **Zip:** 46901 **County Number:** 34
VIN: 1FDWE35P66HA03798 **License Number:** 21218 **Bus Number:** 108
Make of Body: Ford **Year:** 2005 **Make of Chassis:** Ford **Year:** 2006
Bus Type: A2 **Mileage:** 78182
Inspection Status: O **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-4 | The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.