

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/22/2018 **Time:** 9:34 AM
Name of School Corporation: LINCOLN HILLS DEV. CENTER **Corp ID:** 62002Z
Address of School Corporation: 302 Main St
City: Tell City **Zip:** 47586 **County Number:** 62
VIN: 1GBJG31U931110180 **License Number:** 19280 **Bus Number:** 14
Make of Body: Mid Bus, Inc. **Year:** 2003 **Make of Chassis:** Chevrolet **Year:** 2003
Bus Type: A2 **Mileage:** 94386
Inspection Status: O **Inspected By:** Kelly Hammond **PE:** 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
33-1-1	The grill has any exposed edges that may cause injury
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.