

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/26/2018	<b>Time:</b> 2:23 PM
<b>Name of School Corporation:</b> NETTLE CREEK SCHOOL CORP.	<b>Corp ID:</b> 898305	
<b>Address of School Corporation:</b> 795 Baker Rd		
<b>City:</b> Hagerstown	<b>Zip:</b> 47346	<b>County Number:</b> 89
<b>VIN:</b> 4drbuaan4db335703	<b>License Number:</b> 14607	<b>Bus Number:</b> 6
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2012	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2012		
<b>Bus Type:</b> C	<b>Mileage:</b> 57983	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**