

REPORT OF SCHOOL BUS INSPECTION

| | | |
|---|--------------------------------|--|
| Type of Inspection: Post-Crash Inspection | Date: 3/6/2018 | Time: 8:42 AM |
| Name of School Corporation: CENTER GROVE COMM. SCHOOL CORP | Corp ID: 414205 | |
| Address of School Corporation: 4900 W Stones Crossing Rd | | |
| City: Greenwood | Zip: 46143 | County Number: 41 |
| VIN: 4DRBUC8N3KB347985 | License Number: 21829 | Bus Number: 60 |
| Make of Body: IC Corporation | Year: 2017 | Make of Chassis: IC Corporation |
| Year: 2019 | Mileage: 4820 | PE: 6196 |
| Bus Type: C | Inspected By: John Pang | |
| Inspection Status: O | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 70-2-1 | Any glass or glazing is broken through or missing |
| 25-2-1 | Mountings are broken or bent badly enough to inhibit proper adjustment |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.