

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/6/2018	Time:	8:42 AM		
Name of School Corporation:	CENTER GROVE COMM. SCHOOL CORP			Corp ID:	414205		
Address of School Corporation:	4900 W Stones Crossing Rd						
City:	Greenwood	Zip:	46143	County Number:	41		
VIN:	4DRBUC8N3KB347985		License Number:	21829	Bus Number:	60	
Make of Body:	IC Corporation	Year:	2017	Make of Chassis:	IC Corporation	Year:	2019
Bus Type:	C			Mileage:	4820		
Inspection Status:	O	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.