

## REPORT OF SCHOOL BUS INSPECTION

|                                                                   |                                |                                   |
|-------------------------------------------------------------------|--------------------------------|-----------------------------------|
| <b>Type of Inspection:</b> Annual                                 | <b>Date:</b> 3/6/2018          | <b>Time:</b> 11:14 AM             |
| <b>Name of School Corporation:</b> CENTER GROVE COMM. SCHOOL CORP | <b>Corp ID:</b> 414205         |                                   |
| <b>Address of School Corporation:</b> 4900 W Stones Crossing Rd   |                                |                                   |
| <b>City:</b> Greenwood                                            | <b>Zip:</b> 46143              | <b>County Number:</b> 41          |
| <b>VIN:</b> 1GBJG312161238075                                     | <b>License Number:</b> 84277   | <b>Bus Number:</b> 205            |
| <b>Make of Body:</b> Mid Bus, Inc.                                | <b>Year:</b> 2007              | <b>Make of Chassis:</b> Chevrolet |
| <b>Year:</b> 2007                                                 | <b>Bus Type:</b>               | <b>Mileage:</b> 42668             |
| <b>Inspection Status:</b> A                                       | <b>Inspected By:</b> John Pang | <b>PE:</b> 6196                   |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|