## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 3/6/2018 Time: 10:34 AM

Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375

**Address of School Corporation:** 5494 E SR 58

City:
Elnora
Zip:
47529
County Number:
14

VIN:
4DRBUC8P4GB734618
License Number:
000
Bus Number:
ND7

IC
NOT
N

Make of Body: Year: 2014 Make of Chassis: IC Corporation Year: 2016

Bus Type: C Mileage: 32989

Inspection Status: R Inspected By: Kelly Hammond PE: 6682

## **Violations - Rejected**

Inspection Code Description

70-1-10 If the emergency window instructions are illegible or missing. Must be within 6 inches

of the release handle

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.