REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	3/6/2018	**Time:** 11:49 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL				**Corp ID:** 141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529		**County Number:** 14
VIN:	1FDWE35P55HA51789		**License Number:**	69262	**Bus Number:** ND5
Make of Body:	Mid Bus, Inc. **Year:**	2005	**Make of Chassis:**	Ford	**Year:** 2005
Bus Type:			**Mileage:**	72479	
Inspection Status:	O	**Inspected By:**	Kelly Hammond		**PE:** 6682

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

Bus Type Description