

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection      Date: 3/8/2018      Time: 9:11 AM  
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL      Corp ID: 161655  
Address of School Corporation: 1645 W SR 46  
City: Greensburg      Zip: 47240      County Number: 16  
VIN: 4DRBBABP93B581702      License Number: B578L      Bus Number: 21  
Make of Body: IC Corporation      Year: 2004      Make of Chassis: IC Corporation      Year: 2004  
Bus Type: C      Mileage: 98752  
Inspection Status: O      Inspected By: Chris Clark      PE: 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
46-2-2	Any seat is broken or not attached to the floor
11-2-2	A bumper does not meet manufactures specifications
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.