

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 3/8/2018	Time: 9:11 AM
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL	Corp ID: 161655	
Address of School Corporation: 1645 W SR 46		
City: Greensburg	Zip: 47240	County Number: 16
VIN: 4DRBBABP93B581702	License Number: B578L	Bus Number: 21
Make of Body: IC Corporation	Year: 2004	Make of Chassis: IC Corporation
Year: 2004	Mileage: 98752	Year: 2004
Bus Type: C		
Inspection Status: O	Inspected By: Chris Clark	PE: 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
46-2-2	Any seat is broken or not attached to the floor
11-2-2	A bumper does not meet manufactures specifications
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.