

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/9/2018	Time:	1:20 PM		
Name of School Corporation:	BAUGO COMMUNITY SCHOOLS			Corp ID:	202260		
Address of School Corporation:	29125 CR 22 W						
City:	Elkhart	Zip:	46517	County Number:	20		
VIN:	4DRBUAAN36B187627		License Number:	7	Bus Number:	5	
Make of Body:	IC Corporation	Year:	2005	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	C			Mileage:	115670		
Inspection Status:	O	Inspected By:	Wes Rowlader	PE:	7427		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
90-1-2	The trash container is greater than a fourteen (14) quart capacity
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
22-1-1	A dripping oil or fluid leak
7-1-5	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
34-1-1	Any headlight is inoperative
36-1-1	The latch does not secure the hood tightly
4-1-2	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
68-1-3	Reservoir is empty

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-1	Any crossmember is cracked or broken
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.