

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/16/2018 **Time:** 9:28 AM
Name of School Corporation: MANCHESTER COMMUNITY SCHOOLS **Corp ID:** 858045
Address of School Corporation: PO Box 308
City: North Manchester **Zip:** 46962 **County Number:** 85
VIN: 4UZABRDUXDCBZ7469 **License Number:** 4340 **Bus Number:** 7
Make of Body: Thomas Built Buses, Inc. **Year:** 2012 **Make of Chassis:** Freightliner **Year:** 2013
Bus Type: C **Mileage:** 109331
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.