

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/20/2018	<b>Time:</b>	10:10 AM
<b>Name of School Corporation:</b>	GARRETT-KEYSER-BUTLER COMM SCH			<b>Corp ID:</b>	171820
<b>Address of School Corporation:</b>	801 E Houston St				
<b>City:</b>	Garrett	<b>Zip:</b>	46738	<b>County Number:</b>	17
<b>VIN:</b>	1BABKCKA18F247976	<b>License Number:</b>	20599	<b>Bus Number:</b>	3
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	D	<b>Mileage:</b>	116751	<b>Year:</b>	2007
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Eric Egbert	<b>PE:</b>	7006

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is permissible on bumper below door if insufficient space on body)
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-9	There is any defect not in compliance with the minimum school bus brake inspection standards

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**