REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 3/21/2018 Time: 11:34 AM

Name of School Corporation: DELAWARE COMM. SCHOOL CORP. Corp ID: 181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRAPSKH7CB591740License Number:5559Bus Number:3Make of Body:IC Corporation Year:2012
Make of Chassis: IC Corporation Year:

Bus Type: Mileage: 44835

Inspection Status: A Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description