

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/29/2018	Time: 9:52 AM
Name of School Corporation: KOKOMO SCHOOL CORPORATION	Corp ID: 343500	
Address of School Corporation: 620 W Deffenbaugh		
City: Kokomo	Zip: 46901	County Number: 34
VIN: 4DRBUSKN3BB262034	License Number: 74868	Bus Number: 211
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation
Year: 2010		
Bus Type: C	Mileage: 92207	
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-5	Prohibited area sign is missing or obscured
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.