REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual			Date:	4/3/2018	Time:	7:59 AM
Name of School Corporation: HAI		OVER COMM. S	SCHOOL CORP.		Corp ID:	454580
Address of School	Corporation:	PO Box 645				
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	4DRAPSKK89A666	780	License Number:	32985	Bus Number:	21
Make of Body:	IC Corporation Year	: 2007	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	С		Mileage:	64029		
Inspection Status:	R	Inspected By:	Tim Grayson		PE:	7558

Violations - Rejected

Inspection CodeDescription23-1-5Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.