

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/3/2018	<b>Time:</b>	8:06 AM
<b>Name of School Corporation:</b>	HANOVER COMM. SCHOOL CORP.			<b>Corp ID:</b>	454580
<b>Address of School Corporation:</b>	PO Box 645				
<b>City:</b>	Cedar Lake	<b>Zip:</b>	46303	<b>County Number:</b>	45
<b>VIN:</b>	4UZABRCS87CX72413	<b>License Number:</b>	20516	<b>Bus Number:</b>	16
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	75597	<b>Year:</b>	2007
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Tim Grayson	<b>PE:</b>	7558

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**