## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual			Date:	4/3/2018	Time:	9:16 AM
Name of School Corporation:		HAN	OVER COMM.	SCHOOL CORP.		Corp ID:	454580
Address of School Corporation:		PO Box 645					
City:	Cedar Lake		Zip:	46303		County Number:	45
VIN:	4UZABRFC4JCJU1847	7		License Number:	17901	Bus Number:	11
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Freightliner	Year:	2018
Bus Type:	С			Mileage:	13587		
Inspection Status	s: O		Inspected By:	Tim Grayson		PE:	7558

## **Violations - Rejected**

Inspection Code Description

## Violations - Out of Service

Inspection<br/>CodeDescription7-2-4Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at<br/>other than a proper connection).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.