## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:4/3/2018Time:8:41 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1HVBBAAP0XH648402License Number:16385Bus Number:51Make of Body:AmTran Year:1999Make of Chassis:IC Corporation Year:1999

Bus Type: C Mileage: 175234

Inspection Status: R Inspected By: Kelly Hammond PE: 6682

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

35-1-1 A heater motor is not operating properly

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.