REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	4/3/2018	Time:	9:55 AM
Name of Schoo Address of Sch	I Corporation: CRA		COMM. SCHO	OL CORP	Corp ID:	131300
City:	Marengo	Zip:	47140		County Number:	13
VIN:	4UZABRDU89CAH7995		License Number:	32269	Bus Number:	53
Make of Body:	Thomas Built Buses, Yea Inc.	r : 2009	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2009
Bus Type:	С		Mileage:	100701		
Inspection Status:	0	Inspected By:	Kelly Hammon	d	PE:	6682

Violations - Rejected

Inspection Code	Description			
70-1-7	Any emergency window is too difficult to open			
49-1-3	The reflective material is not National School Bus Yellow or white if on an MFSAB, or Black if on a bumper.			

Violations - Out of Service

Inspection Code	Description
59-2-4	Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.