

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 4/3/2018	<b>Time:</b> 9:55 AM
<b>Name of School Corporation:</b> CRAWFORD CO. COMM. SCHOOL CORP	<b>Corp ID:</b> 131300	
<b>Address of School Corporation:</b> 5808 E Administration Rd		
<b>City:</b> Marengo	<b>Zip:</b> 47140	<b>County Number:</b> 13
<b>VIN:</b> 4RDBUSKPXEB405437	<b>License Number:</b> 55NEW	<b>Bus Number:</b> 55
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2014	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2014	<b>Mileage:</b> 85933	<b>Year:</b> 2014
<b>Bus Type:</b> C		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Kelly Hammond	<b>PE:</b> 6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
87-1-1	The safety detection system does not operate automatically when the bus is at a complete stop, with the stop arm extended
32-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**