

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|-------------|-------------------------|-----------------------|--------------|------|
| Type of Inspection: | Annual | Date: | 4/3/2018 | Time: | 10:00 AM | | |
| Name of School Corporation: | SOUTH DEARBORN COMM. SCH. CORP | | | Corp ID: | 151600 | | |
| Address of School Corporation: | 6109 Squire Place | | | | | | |
| City: | Aurora | Zip: | 47001 | County Number: | 15 | | |
| VIN: | 1BABNCPA6CF287284 | License Number: | b137g | Bus Number: | 30 | | |
| Make of Body: | Blue Bird Corporation | Year: | 2011 | Make of Chassis: | Blue Bird Corporation | Year: | 2012 |
| Bus Type: | B | Mileage: | 50192 | | | | |
| Inspection Status: | A | Inspected By: | Chris Clark | PE: | 6665 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.