## REPORT OF SCHOOL BUS INSPECTION

Type of 8:45 Annual 4/4/2018 **Time**: Date: Inspection: AM CRAWFORD CO. COMM. SCHOOL CORP Name of School Corporation: Corp ID: 131300 **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1GBJG31K091163308 81641 **Bus Number:** 85 Number: Make of Collins Bus Year: 2009 Chevrolet Year: Make of Body: 2009 Corporation Chassis: **Bus Type:** Α1 Mileage: 89569 Inspected PE: 6682 **Inspection Status:** R Kelly Hammond By:

## Violations - Rejected

Inspection Code	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
68-1-3	Reservoir is empty

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.