REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:4/4/2018Time:9:27 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1HVBBAAP0XH232236License Number:B574LBus Number:33Make of Body:AmTranYear:1999Make of Chassis:IC CorporationYear:1999

Bus Type: C Mileage: 142127

Inspection Status: A Inspected By: Mark Raper PE: 6473

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.