

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/4/2018 Time: 9:37 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo Zip: 47140 County Number: 13
VIN: 1HVBABP8XH208703 License Number: B616M Bus Number: 1
Make of Body: IC Corporation Year: 1999 Make of Chassis: AmTran Year: 1999
Bus Type: C Mileage: 145593
Inspection Status: R Inspected By: Mark Raper PE: 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
25-1-1	Mirror or mirror backs that are loose or improperly mounted

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.