

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/4/2018	Time: 9:37 AM	
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300		
Address of School Corporation: 5808 E Administration Rd			
City: Marengo	Zip: 47140	County Number: 13	
VIN: 1HVBBABP8XH208703	License Number: B616M	Bus Number: 1	
Make of Body: IC Corporation	Year: 1999	Make of Chassis: AmTran	Year: 1999
Bus Type: C	Mileage: 145593		
Inspection Status: R	Inspected By: Mark Raper	PE: 6473	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
25-1-1	Mirror or mirror backs that are loose or improperly mounted

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.