

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/4/2018	Time:	10:16 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	1GB3G2BG6B1170668	License Number:	G653896	Bus Number:	50
Make of Body:	Collins Bus Corporation	Year:	2011	Make of Chassis:	Collins Bus Corporation
Bus Type:	A2			Mileage:	56724
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.