

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/5/2018	Time:	12:26 PM
Name of School Corporation:	SOUTHERN WELLS COMM. SCHOOLS	Corp ID:	908425		
Address of School Corporation:					
City:	Zip:			County Number:	90
VIN:	4DRBUAAN3EB416872	License Number:	6470	Bus Number:	14
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Year:			2014	Year:	2014
Bus Type:	C	Mileage:	38148		
Inspection Status:	O	Inspected By:	Jamie Hotchkiss	PE:	6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
30-1-3	See Notes: Any defect inspector deems a violation not listed
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-1	Any glass or glazing is broken through or missing
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.