

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/9/2018	Time:	12:43 PM
Name of School Corporation:	BROWNSBURG COMM. SCHOOL CORP.			Corp ID:	323305
Address of School Corporation:	310 Stadium Drive				
City:	Brownsburg	Zip:	46112	County Number:	32
VIN:	1T7YT4E2991114844	License Number:	30061	Bus Number:	87
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	81704
Inspection Status:	O	Inspected By:	John Pang	PE:	6196

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.