

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/13/2018	<b>Time:</b> 9:53 AM
<b>Name of School Corporation:</b> CENTERVILLE-ABINGTON COMM SCHS	<b>Corp ID:</b> 898360	
<b>Address of School Corporation:</b> 116 W SOUTH ST		
<b>City:</b> CENTERVILLE	<b>Zip:</b> 47330	<b>County Number:</b> 89
<b>VIN:</b> 1HVBBABN6YH290835	<b>License Number:</b> 17297	<b>Bus Number:</b> M5
<b>Make of Body:</b> Carpenter	<b>Year:</b> 2000	<b>Make of Chassis:</b> IC Corporation
<b>Bus Type:</b> B	<b>Mileage:</b> 62371	<b>Year:</b> 2000
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**