REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection 4/23/2018 **Time**: Date: 9:42 AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 City: Elnora Zip: 47529 **County Number: 14** VIN: 4UZAAXBV62CJ97773 License Number: D784792 **Bus Number:** 16 Make of Body: Freightliner Year: 2001 Make of Chassis: Freightliner Year: 2002 **Bus Type:** С Mileage: 162991 **Inspection Status:** R PE: 6682 Inspected By: Kelly Hammond

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|--|
| 75-1-4 | Fan strikes the protective cage |
| 15-1-1 | The defroster system is not working properly. |
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |
| 35-1-1 | A heater motor is not operating properly |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.