REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks 4/23/2018 **Time**: Date: 10:08 AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 City: Elnora Zip: 47529 **County Number: 14** VIN: 4UZAAXBV62CJ97773 License Number: D784792 **Bus Number:** 16 Make of Body: Freightliner Year: 2001 Make of Chassis: Freightliner Year: 2002

Bus Type: C Mileage: 162991

Inspection Status: R Inspected By: Kelly Hammond PE: 6682

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|--|
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |
| 15-1-1 | The defroster system is not working properly. |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |
| 35-1-1 | A heater motor is not operating properly |
| 26-1-4 | Not securely mounted |
| 75-1-4 | Fan strikes the protective cage |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.