REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	**Date:**	4/23/2018	**Time:**	10:08 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	4UZAAXBV62CJ97773	**License Number:**	D784792	**Bus Number:**	16
Make of Body:	Freightliner **Year:** 2001	**Make of Chassis:**	Freightliner	**Year:**	2002
Bus Type:	C	**Mileage:**	162991		
Inspection Status:	R	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
15-1-1	The defroster system is not working properly.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
35-1-1	A heater motor is not operating properly
26-1-4	Not securely mounted
75-1-4	Fan strikes the protective cage

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.