## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection:         | Annual                      |                           |                  | Date:              | 4/23/2018    | Time:             | 11:28<br>AM |
|--------------------------------|-----------------------------|---------------------------|------------------|--------------------|--------------|-------------------|-------------|
| Name of School Corporation:    |                             | TRITON SCHOOL CORPORATION |                  |                    | Corp ID:     | 505495            |             |
| Address of School Corporation: |                             | 100 Triton Dr             |                  |                    |              |                   |             |
| City:                          | Bourbon                     |                           | Zip:             | 46504              |              | County<br>Number: | 50          |
| VIN:                           | 4UZABRDU7GCHF5830           |                           |                  | License<br>Number: | 5620         | Bus Number:       | 19          |
| Make of Body:                  | Thomas Built Buses,<br>Inc. | Year:                     | 2015             | Make of Chassis:   | Freightliner | Year:             | 2016        |
| Bus Type:                      | С                           |                           |                  | Mileage:           | 34738        |                   |             |
| Inspection<br>Status:          | R                           |                           | Inspected<br>By: | Travis Harrold     |              | PE:               | 8022        |

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

64-1-4 Any front turn signal does not function properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.